

SOW CHANGE PROPOSAL

SOW-03-834-1-8G828B-1/1	Change 1	5 March 2003
SOW-04-CBG-8G828B-1/1	Change 1	5 March 2003
SOW-05-PMM143-8G828B-1/1	Change 1	5 March 2003


STATEMENTS OF WORK (SOW's)
for the
REBUILD
of the
M36E3 Head Assembly
NSN 1240-01-387-6728

SOW-03-834-1-8G828B-1/1 Change 1
SOW-04-CBG-8G828B-1/1 Change 1
SOW-05-PMM143-8G828B-1/1 Change 1

Wherever Identification Number (ID) 8G828B appears in the document, change it to read 8G282B. The ID was transposed and the deficiency has just been identified. ID 8G282B is the correct ID for NSN 1240-01-387-6728, M36E3 Head Assembly.

If approved, does this proposed change have the potential to have an impact on the cost or schedule?
Yes ☐ or No ☒


Change Submitted by:



5 March 2003

R. E. Hoffman
Equipment Specialist
AAVS/AFSS (Code PMM142)
MARCORSYSCOM, Albany GA

Change Approved by



5 March 2003

R. E. Hoffman
Logistics Management Specialist (Acting)
AAVS/AFSS (Code PMM142)
MARCORSYSCOM, Albany GA